PRINTED: 09/28/2011 FORM APPROVED OMB NO. 0938-0391

| STATEMENT OF DEFICIENCIES | | X1) PROVIDER/SUPPLIER/CLIA | (X2) MULTIPLE CONSTRUCTION | | ONSTRUCTION | (X3) DATE SURVEY | | |
|------------------------------|---|------------------------------|--------------------------------|-----|---|------------------|------------|--|
| AND PLAN OF CORRECTION | | IDENTIFICATION NUMBER: | TIFICATION NUMBER: A. BUILDING | | 01 | | COMPLETED | |
| | | 15G452 | A. BUILDING B. WING | | | 09/07/2011 | | |
| | | | D. WIIV | | ADDRESS, CITY, STATE, ZIP CODE | | | |
| NAME OF PROVIDER OR SUPPLIER | | | | | HIGHLAND DR | | | |
| DUNGARVIN INDIANA LLC | | | SOUTH BEND, IN46635 | | | | | |
| (X4) ID | SUMMARY STATEMENT OF DEFICIENCIES | | ID PREFIX | | PROVIDER'S PLAN OF CORRECTION | | (X5) | |
| PREFIX | (EACH DEFICIENCY MUST BE PERCEDED BY FULL | | | | (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) | ΤΕ | COMPLETION | |
| TAG | REGULATORY OR | LSC IDENTIFYING INFORMATION) | | TAG | DEFICIENC!) | | DATE | |
| K0000 | | | | | | | | |
| | A Life Safety Code Recertification | | K0000 | | | | | |
| | Survey was co | onducted by the | | | | | | |
| | <u> </u> | Department of Health | | | | | | |
| | in accordance | • | | | | | | |
| | 483.470(j). | WIMI 12 OI IX | | | | | | |
| | 463.470(j). | | | | | | | |
| | Survey Date: 09/07/11 | | | | | | | |
| | Survey Date. 09/0//11 | | | | | | | |
| | Facility Number: 000966 | | | | | | | |
| | Provider Num | ber: 15G452 | | | | | | |
| | | | | | | | | |
| | AIM Number: 100244770 | | | | | | | |
| | Surveyor: Richard D. Schade, Life | | | | | | | |
| | | pecialist, Chris | | | | | | |
| | • | pecianst, Chris | | | | | | |
| | Greeny | | | | | | | |
| | At this Life Safety Code survey, | | | | | | | |
| | Dungarvin Indiana, LLC was found | | | | | | | |
| | - | | | | | | | |
| | not in complia | | | | | | | |
| | - | for Participation in | | | | | | |
| | Medicaid, 42 | CFR Subpart | | | | | | |
| | 483.470(j), Lii | fe Safety from Fire | | | | | | |
| | | edition of the National | | | | | | |
| | | n Association (NFPA) | | | | | | |
| | | · · · · · · | | | | | | |
| | | ty Code (LSC), | | | | | | |
| | _ | xisting Residential | | | | | | |
| | Board and Care Occupancies. | | | | | | | |
| | | | | | | | | |

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determined that other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YTCY21

Facility ID:

000966

If continuation sheet

PRINTED: 09/28/2011 FORM APPROVED OMB NO. 0938-0391

| I ' | | XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G452 | (X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING | | (X3) DATE SURVEY COMPLETED 09/07/2011 | | | |
|---|--|--|---|---|---|--|--|--|
| NAME OF PROVIDER OR SUPPLIER DUNGARVIN INDIANA LLC | | | STREET ADDRESS, CITY, STATE, ZIP CODE 52812 HIGHLAND DR SOUTH BEND, IN46635 | | | | | |
| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) | (X5) COMPLETION DATE | | | |
| | sprinklered. Talarm system win the corridor areas. The face 8 and had a ce of this survey. Calculation of Difficulty Scot NFPA 101A, A Approaches to 6, rated the face E-Score of 0.3 Quality Review by I Code Specialist-Med The facility was compliance with aforementione | Life Safety, Chapter cility Prompt with an 5. Robert Booher, Life Safety dical Surveyor on 09/12/11. as found not in the the | | | | | | |
| K0130 | Događ on obco | ryotion and | K0130 | The Program Director, | 10/07/2011 | | | |
| | Based on obse interview, the | facility failed to | KUISU | Maintenance Director, and L Counselor will be retrained | ₋ead | | | |

PRINTED: 09/28/2011 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED 01 A. BUILDING 15G452 09/07/2011 B. WING STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 52812 HIGHLAND DR **DUNGARVIN INDIANA LLC** SOUTH BEND, IN46635 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) PREFIX COMPLETION PREFIX (EACH DEFICIENCY MUST BE PERCEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DATE expectation. The fire ensure 2 of 2 portable fire extinguishers in the home will be extinguishers were provided checked monthly for compliance maintenance at least annually. with this code, and the Program Director will ensure that the NFPA 101, Section 4.5.7, requires annual inspection is completed any device, equipment or system timely going forward. This will be documented on the Monthly Site required for compliance with this Risk Management checklist, and Code shall thereafter be maintained a copy of this checklist will be given to the Program Coordinator unless the Code exempts such for review and follow up.System maintenance. NFPA 10, Standard wide, all Program Director/QMRP's will review this for Portable Fire Extinguishers, standard and ensure that this 4-4.1 requires extinguishers shall requirement is being applied to all be subjected to maintenance at Dungarvin ICF-MR's.Persons Responsible: Program Director, intervals of not more than 1 year, at Maintenance Director, Lead the time of hydrostatic test, or when Counselor specifically indicated by an inspection. This deficient practice affects all staff, visitors and clients. Findings include: Based on observation on 09/07/11 at 11:25 a.m. with the home manager, the portable fire extinguishers located near the kitchen and the sleeping room corridor had attached documentation of an annual inspection completed in June of 2010. The home manager stated at

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YTCY21

Facility ID:

000966 If cor

If continuation sheet Page 3 of 4

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/28/2011 FORM APPROVED OMB NO. 0938-0391

| | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G452 | (X2) MULTIPLE CO A. BUILDING B. WING | 01 | (X3) DATE SURVEY COMPLETED 09/07/2011 |
|--------------------------|----------------------|---|--|--|---------------------------------------|
| | PROVIDER OR SUPPLIER | | 52812 I | ADDRESS, CITY, STATE, ZIP COI HIGHLAND DR I BEND, IN46635 | DE |
| (X4) ID PREFIX TAG | (EACH DEFICIEN | STATEMENT OF DEFICIENCIES ICY MUST BE PERCEDED BY FULL LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRI (EACH CORRECTIVE ACTION SHE CROSS-REFERENCED TO THE AP DEFICIENCY) | OULD BE COMPLETION |
| | not aware the | e interview, she was annual inspection of re extinguishers was | | | |